

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS  
OHIO,  
31-CINT,  
29-A-

Cincinnati Union Terminal,  
Mail Handling Building  
Bounded by vacated McLean Avenue,  
Sherman Avenue, vacated Liberty Avenue and  
the Conrail railroad tracks  
Cincinnati  
Hamilton County  
Ohio

HABS No. OH-705-A

Photographer: David M. Thum

October 1988

- OH-705-A-1      View east and south, distant view of the Union Terminal complex.
- OH-705-A-2      View northwest, aerial view of entire building.
- OH-705-A-3      View northwest, south and east facades.
- OH-705-A-4      View east, south and west facades.
- OH-705-A-5      View southeast, east and north facades.
- OH-705-A-6      View west, north facade.
- OH-705-A-7      View south, interior, ground floor, column detail.
- OH-705-A-8      View southwest, interior, ground floor, overall view.
- OH-705-A-9      View north, interior, clerestory detail.
- OH-705-A-10      View southwest, interior, clerestory detail.
- OH-705-A-11      View southeast, interior, main floor.
- OH-705-A-12      View west, interior, main floor.
- OH-705-A-13      View south, interior, main floor.
- OH-705-A-14      Photocopy of a lithograph from the 1932 terminal brochure, view north, Mail Handling Building and Passageway.
- OH-705-A-15      Photocopy of a lithograph from the 1932 terminal brochure, exterior view northeast and interior view of the main floor.
- OH-705-A-16      Photocopy of a lithograph from the 1932 terminal brochure, aerial view, north.

Cincinnati Union Terminal,  
Mail Handling Building  
HABS No. OH-705-A (Page 2)  
Index to Photographs

ADDENDUM: SITE PLAN WITH KEY TO PHOTO VIEWS

